

## W4800

Low Activity Weigh Scale for belt conveyors and screw conveyors

The W4800 utilizes low levels of radiation to measure weight of material on/in belt conveyors, screw conveyors and other types of material handling systems. An auxiliary input representing belt or screw speed enables the W4800 to output a mass flow signal. Totalized weight can also be generated through a pulse output.





## Accessories, Software and Spare Parts - Weight

### Cable:

CABLE.202676	BELDEN 8760 18AWG 2 CONDUCTOR 300V. Used to connect frequency or current signals to SmartPro remote electronics or to user's PLC/DCS unit. Specify length in 1 foot (305mm) increments. Price per foot.
CABLE.202679	Tray Cable - Belden 9341: 18AWG X 2 conductors, twisted pair, 600V, shielded, UV resistant jacket. Used to connect frequency or current signals to SmartPro remote electronics or to user's PLC/DCS input. Specify length in 1 foot (305mm) increments. Price per foot.

### Manuals:

Additional copies of manuals on CD  
 Additional copies of paper manuals

### Software:

244400.	Ohmview Software with USB HART modem
---------	--------------------------------------

### Recommended Spare Parts:

242281.	Spare electronics: CPU circuit board, Frequency version
239622.	Spare electronics: CPU circuit board, HART version
247658.	Spare electronics: CPU circuit board, HART version (UG)
241519.	Spare electronics: Power supply circuit board
247661.	Spare electronics: Power supply circuit board, HART version (UG)

